

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:					
Company	Rusty Netz Environmental Coordinator				
Other	S. Scott Carlson Project Director				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0070035		
Inspection Type:	COMPLETE		
Inspection Date:	Friday, March 25, 2005		
Start Date/Time:	3/25/2005 12:00:00 PM		
End Date/Time:	3/25/2005 4:00:00 PM		
Last Inspection:	Tuesday, February 15, 2005		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Snowing, Temp 30 Deg F

InspectionID Report Number: 570

Accepted by: pgrubaug 3/31/2005

Permitee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages Mineral Ownership Types of Operations

310.00	Total Permitted	☐ Federal	☐ Underground
202.00	Total Disturbed	☐ State	Surface
	Phase I	☐ County	Loadout
	Phase II	✓ Fee	Processing
	Phase III	☐ Other	✓ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Inspector's Signature Date Friday, March 25, 2005

Karl Houskeeper, Environmental Scientist III Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070035 Inspection Type: COMPLETE

Inspection Date: Friday, March 25, 2005

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓		✓	
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control		✓		
15.	Cessation of Operations	✓			
16.	a Roads: Construction, Maintenance, Surfacing	~			
16.	o Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	~			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other	✓			

Permit Number: C0070035 Inspection Type: COMPLETE

Inspection Date: Friday, March 25, 2005

1. Permits, Change, Transfer, Renewal, Sale

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

The following permits were reviewed:

- -Mining permit C/007/035 issued February 4, 2003 and expires February 4, 2008.
- -UPDES permit #UT0024759 effective August 1, 2002 and expires midnight July 31, 2007.
- -Air Quality Permit DAQO-702038-02 issued November 1, 2002, remains in effect.
- -SPCC plan is only applicable to plant site which is not within the permit area.
- -Certificate of Insurance effective 08/01/2004 and terminates 08/01/2005.
- -Reclamation agreement is dated December 1996 and signed by both parties.

2. Signs and Markers

The mine ID sign is located adjacent to the tipple on a light pole. The MSHA Refuse and Impoundment signs were also checked during the inspection and contained the required information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The first quarter 2005 inspection of the sediment ponds was done in conjunction with the Division complete inspection by Scott Carlson a registered professional engineer in the State of Utah.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2004 water monitoring is in the EDI website and uploaded. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

The January 2005 discharge monitoring reports showed that no discharges occurred from any of the outfalls.

6. Disposal of Excess Spoil, Fills, Benches

Excess spoil area #2 remains active and excess spoil area #1 is inactive. The operator is still desirous to increase the size of excess spoil area #2. The application that the Division sent back to the operator is in the process of being evaluated for resubmission.

7. Coal Mine Waste, Refuse Piles, Impoundments

Mining of the refuse pile is still taking place in pockets according to fuel needs at the power plant. The pile appeared stable with no visible hazards.

Permit Number: C0070035 Inspection Type: COMPLETE

Inspection Date: Friday, March 25, 2005 Page 4 of 4

20. Air Quality Permit

DAQO-702038-02 issued November 1, 2002, remains in effect. Air Quality Permit DAQE-691-99 issued August 13, 1999 was replaced by DAQO-702038-02. The permit was modified to allow the usage of a diesel generator on the power plant site. The Air Quality Permit covers both the power plant and mine site. The power plant site is not regulated by DOGM.

21. Bonding and Insurance

A Pledge and Escrow agreement dated January 4, 2002 is in place. This agreement is between Wells Fargo and the Division of Oil, Gas and Mining on behalf of SCA. SCA has invested \$1,747,000 in federally guaranteed Treasury Notes. The required bond amount is \$1,720,000.

Insurance for the site is under Federal Insurance Company, policy #3581-69-76. The policy was issued on August 1, 2004 and expires on August 1, 2005. The policy meets all the minimum requirements of the coal rules. No explosives coverage is noted on the insurance form. However, the MRP clearly identifies that all issues regarding explosives are not addressed, since explosives will not be used at the site. The certificate holder is listed as the State of Utah, Division of Oil, Gas and Mining.